



## Appendix F-4 Existing Driveway Counts



*This page intentionally left blank.*



City: Costa Mesa  
 Location: Sunflower Avenue  
 Driveway: #1  
 Date: Wednesday 11 Sept 2019  
 Count Type: Driveway Classification

	Entering				
	Pass Veh	Large 2 Axle	3 Axle	4+ Axle	Total
0:00	0	0	0	0	0
0:15	0	0	0	0	0
0:30	0	0	0	0	0
0:45	0	0	0	0	0
1:00	0	0	0	0	0
1:15	0	0	0	0	0
1:30	0	0	0	0	0
1:45	0	0	0	0	0
2:00	0	0	0	0	0
2:15	0	0	0	0	0
2:30	0	0	0	0	0
2:45	0	0	0	0	0
3:00	0	0	0	0	0
3:15	0	0	0	0	0
3:30	0	0	0	0	0
3:45	0	0	0	0	0
4:00	0	0	0	0	0
4:15	0	0	0	0	0
4:30	0	0	0	0	0
4:45	0	0	0	0	0
5:00	0	0	0	0	0
5:15	0	0	0	0	0
5:30	3	0	0	0	3
5:45	6	0	0	0	6
6:00	3	0	0	0	3
6:15	0	0	0	0	0
6:30	1	0	0	0	1
6:45	4	0	0	0	4
7:00	10	0	0	0	10
7:15	4	0	0	0	4
7:30	11	0	0	0	11
7:45	13	0	0	0	13
8:00	3	0	0	0	3
8:15	2	0	0	0	2
8:30	1	0	0	0	1
8:45	2	0	0	0	2
9:00	1	0	0	0	1
9:15	2	0	0	0	2
9:30	2	0	0	0	2
9:45	2	1	0	0	3
10:00	6	0	0	0	6
10:15	2	0	0	0	2
10:30	0	0	0	0	0
10:45	1	0	0	0	1
11:00	0	0	0	0	0
11:15	5	0	0	0	5
11:30	0	0	0	0	0
11:45	2	0	0	0	2
12:00	1	0	0	0	1
12:15	2	0	0	0	2
12:30	2	0	0	0	2
12:45	3	0	0	0	3
13:00	2	0	0	0	2
13:15	1	1	0	0	2
13:30	0	0	0	0	0
13:45	0	0	0	0	0
14:00	0	0	0	0	0
14:15	1	0	0	0	1
14:30	3	0	0	0	3
14:45	1	1	0	0	2
15:00	0	0	0	0	0
15:15	0	0	0	0	0
15:30	0	0	0	0	0
15:45	2	0	0	0	2
16:00	2	0	0	0	2
16:15	0	0	0	0	0
16:30	1	0	0	0	1
16:45	1	0	0	0	1
17:00	1	0	0	0	1
17:15	0	0	0	0	0
17:30	0	0	0	0	0
17:45	0	0	0	0	0
18:00	0	0	0	0	0
18:15	0	0	0	0	0
18:30	0	0	0	0	0
18:45	0	0	0	0	0
19:00	0	0	0	0	0
19:15	0	0	0	0	0
19:30	0	0	0	0	0
19:45	0	0	0	0	0
20:00	0	0	0	0	0
20:15	0	0	0	0	0
20:30	0	0	0	0	0
20:45	0	0	0	0	0
21:00	0	0	0	0	0
21:15	0	0	0	0	0
21:30	0	0	0	0	0
21:45	0	0	0	0	0
22:00	0	0	0	0	0
22:15	0	0	0	0	0
22:30	0	0	0	0	0
22:45	0	0	0	0	0
23:00	0	0	0	0	0
23:15	0	0	0	0	0
23:30	0	0	0	0	0
23:45	0	0	0	0	0
<b>TOTAL</b>	<b>109</b>	<b>3</b>	<b>0</b>	<b>0</b>	<b>112</b>

	Exiting				
	Pass Veh	Large 2 Axle	3 Axle	4+ Axle	Total
0:00	0	0	0	0	0
0:15	0	0	0	0	0
0:30	0	0	0	0	0
0:45	0	0	0	0	0
1:00	0	0	0	0	0
1:15	0	0	0	0	0
1:30	0	0	0	0	0
1:45	0	0	0	0	0
2:00	0	0	0	0	0
2:15	0	0	0	0	0
2:30	0	0	0	0	0
2:45	0	0	0	0	0
3:00	0	0	0	0	0
3:15	0	0	0	0	0
3:30	0	0	0	0	0
3:45	0	0	0	0	0
4:00	0	0	0	0	0
4:15	0	0	0	0	0
4:30	0	0	0	0	0
4:45	0	0	0	0	0
5:00	0	0	0	0	0
5:15	0	0	0	0	0
5:30	0	0	0	0	0
5:45	1	0	0	0	1
6:00	0	0	0	0	0
6:15	0	0	0	0	0
6:30	0	0	0	0	0
6:45	0	0	0	0	0
7:00	0	0	0	0	0
7:15	0	0	0	0	0
7:30	1	0	0	0	1
7:45	0	0	0	0	0
8:00	0	0	0	0	0
8:15	0	0	0	0	0
8:30	2	0	0	0	2
8:45	1	0	0	0	1
9:00	1	0	0	0	1
9:15	1	0	0	0	1
9:30	1	0	0	0	1
9:45	3	0	0	0	3
10:00	1	0	0	0	1
10:15	3	0	0	0	3
10:30	0	0	0	0	0
10:45	1	0	0	0	1
11:00	4	0	0	0	4
11:15	1	0	0	0	1
11:30	2	0	0	0	2
11:45	6	0	0	0	6
12:00	3	0	0	0	3
12:15	2	0	0	0	2
12:30	4	0	0	0	4
12:45	0	0	0	0	0
13:00	2	0	0	0	2
13:15	0	1	0	0	1
13:30	1	0	0	0	1
13:45	3	0	0	0	3
14:00	1	0	0	0	1
14:15	1	0	0	0	1
14:30	13	0	0	0	13
14:45	2	0	0	0	2
15:00	0	0	0	0	0
15:15	1	0	0	0	1
15:30	3	0	0	0	3
15:45	3	0	0	0	3
16:00	2	0	0	0	2
16:15	16	0	0	0	16
16:30	28	0	0	0	28
16:45	2	0	0	0	2
17:00	0	0	0	0	0
17:15	3	0	0	0	3
17:30	0	0	0	0	0
17:45	4	0	0	0	4
18:00	1	0	0	0	1
18:15	0	0	0	0	0
18:30	1	0	0	0	1
18:45	1	0	0	0	1
19:00	0	0	0	0	0
19:15	0	0	0	0	0
19:30	0	0	0	0	0
19:45	0	0	0	0	0
20:00	0	0	0	0	0
20:15	0	0	0	0	0
20:30	0	0	0	0	0
20:45	0	0	0	0	0
21:00	0	0	0	0	0
21:15	0	0	0	0	0
21:30	0	0	0	0	0
21:45	0	0	0	0	0
22:00	0	0	0	0	0
22:15	0	0	0	0	0
22:30	0	0	0	0	0
22:45	0	0	0	0	0
23:00	0	0	0	0	0
23:15	0	0	0	0	0
23:30	0	0	0	0	0
23:45	0	0	0	0	0
<b>TOTAL</b>	<b>126</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>127</b>

City: Costa Mesa  
 Location: Sunflower Avenue  
 Driveway: #2  
 Date: Wednesday 11 Sept 2019  
 Count Type: Driveway Classification

	Entering				Total
	Pass Veh	Large 2 Axle	3 Axle	4+ Axle	
0:00	0	0	0	0	0
0:15	0	0	0	0	0
0:30	0	0	0	0	0
0:45	0	0	0	0	0
1:00	0	0	0	0	0
1:15	0	0	0	0	0
1:30	0	0	0	0	0
1:45	0	0	0	0	0
2:00	0	0	0	0	0
2:15	0	0	0	0	0
2:30	0	0	0	0	0
2:45	0	0	0	0	0
3:00	0	0	0	0	0
3:15	0	0	0	0	0
3:30	0	0	0	0	0
3:45	0	0	0	0	0
4:00	0	0	0	0	0
4:15	1	0	0	0	1
4:30	0	0	0	0	0
4:45	0	0	0	0	0
5:00	0	0	0	0	0
5:15	1	0	0	0	1
5:30	9	0	0	0	9
5:45	2	0	0	0	2
6:00	1	0	0	0	1
6:15	0	0	0	0	0
6:30	0	0	0	0	0
6:45	0	0	0	0	0
7:00	1	0	0	0	1
7:15	0	0	0	3	3
7:30	2	0	0	0	2
7:45	0	0	0	1	1
8:00	3	0	0	0	3
8:15	0	0	0	0	0
8:30	0	0	0	0	0
8:45	0	0	0	1	1
9:00	0	0	0	0	0
9:15	2	0	0	1	3
9:30	2	1	0	1	4
9:45	0	2	0	1	3
10:00	0	0	0	0	0
10:15	0	1	0	0	1
10:30	0	1	0	1	2
10:45	0	1	0	2	3
11:00	1	1	0	0	2
11:15	0	0	0	1	1
11:30	0	0	0	0	0
11:45	0	1	0	1	2
12:00	1	1	1	1	4
12:15	1	0	0	0	1
12:30	0	1	0	2	3
12:45	0	0	0	1	1
13:00	0	0	0	1	1
13:15	0	2	0	0	2
13:30	0	1	0	0	1
13:45	0	1	0	2	3
14:00	1	2	0	0	3
14:15	0	1	0	1	2
14:30	2	0	0	0	2
14:45	0	0	0	0	0
15:00	1	1	0	0	2
15:15	0	0	0	0	0
15:30	0	1	0	0	1
15:45	1	0	0	0	1
16:00	0	0	0	1	1
16:15	0	0	0	0	0
16:30	0	0	0	0	0
16:45	0	0	0	0	0
17:00	0	0	0	0	0
17:15	0	0	0	0	0
17:30	0	0	0	0	0
17:45	0	0	0	0	0
18:00	0	0	0	0	0
18:15	0	0	0	0	0
18:30	0	0	0	0	0
18:45	0	0	0	0	0
19:00	0	0	0	0	0
19:15	0	0	0	0	0
19:30	0	0	0	0	0
19:45	0	0	0	0	0
20:00	0	0	0	0	0
20:15	0	0	0	0	0
20:30	0	0	0	0	0
20:45	0	0	0	0	0
21:00	0	0	0	0	0
21:15	0	0	0	0	0
21:30	0	0	0	0	0
21:45	0	0	0	0	0
22:00	0	0	0	0	0
22:15	0	0	0	0	0
22:30	0	0	0	0	0
22:45	0	0	0	0	0
23:00	0	0	0	0	0
23:15	0	0	0	0	0
23:30	0	0	0	0	0
23:45	0	0	0	0	0
<b>TOTAL</b>	<b>32</b>	<b>19</b>	<b>1</b>	<b>22</b>	<b>74</b>

	Exiting				Total
	Pass Veh	Large 2 Axle	3 Axle	4+ Axle	
0:00	0	0	0	0	0
0:15	0	0	0	0	0
0:30	0	0	0	0	0
0:45	0	0	0	0	0
1:00	0	0	0	0	0
1:15	0	0	0	0	0
1:30	0	0	0	0	0
1:45	0	0	0	0	0
2:00	0	0	0	0	0
2:15	0	0	0	0	0
2:30	0	0	0	0	0
2:45	0	0	0	0	0
3:00	0	0	0	0	0
3:15	0	0	0	0	0
3:30	0	0	0	0	0
3:45	0	0	0	0	0
4:00	0	0	0	0	0
4:15	0	0	0	0	0
4:30	0	0	0	0	0
4:45	0	0	0	0	0
5:00	0	0	0	0	0
5:15	0	0	0	0	0
5:30	0	0	0	0	0
5:45	0	0	0	0	0
6:00	0	0	0	0	0
6:15	0	0	0	0	0
6:30	0	0	0	0	0
6:45	0	0	0	0	0
7:00	1	0	0	0	1
7:15	0	0	0	0	0
7:30	1	0	0	0	1
7:45	0	0	0	0	0
8:00	1	0	0	0	1
8:15	0	0	0	0	0
8:30	0	0	0	1	1
8:45	0	0	0	1	1
9:00	0	1	0	0	1
9:15	0	0	0	1	1
9:30	0	0	0	1	1
9:45	0	1	0	0	1
10:00	0	0	0	0	0
10:15	1	1	0	0	2
10:30	0	2	0	2	4
10:45	0	1	0	0	1
11:00	0	2	0	0	2
11:15	0	1	0	1	2
11:30	1	0	0	1	2
11:45	1	0	0	1	2
12:00	0	1	0	0	1
12:15	0	1	1	0	2
12:30	0	0	0	1	1
12:45	0	1	0	0	1
13:00	0	0	0	1	1
13:15	0	0	0	3	3
13:30	0	0	0	0	0
13:45	0	2	0	0	2
14:00	0	1	0	2	3
14:15	1	1	0	0	2
14:30	0	2	0	0	2
14:45	1	1	0	0	2
15:00	1	1	0	0	2
15:15	0	0	0	1	1
15:30	3	1	0	0	4
15:45	1	0	0	2	3
16:00	0	0	0	0	0
16:15	0	0	0	1	1
16:30	0	0	0	0	0
16:45	0	0	0	0	0
17:00	0	0	0	0	0
17:15	0	0	0	0	0
17:30	0	0	0	0	0
17:45	0	0	0	0	0
18:00	0	0	0	0	0
18:15	0	0	0	0	0
18:30	0	0	0	0	0
18:45	0	0	0	0	0
19:00	0	0	0	0	0
19:15	0	0	0	0	0
19:30	0	0	0	0	0
19:45	0	0	0	0	0
20:00	0	0	0	0	0
20:15	0	0	0	0	0
20:30	0	0	0	0	0
20:45	0	0	0	0	0
21:00	0	0	0	0	0
21:15	0	0	0	0	0
21:30	0	0	0	0	0
21:45	0	0	0	0	0
22:00	0	0	0	0	0
22:15	0	0	0	0	0
22:30	0	0	0	0	0
22:45	0	0	0	0	0
23:00	0	0	0	0	0
23:15	0	0	0	0	0
23:30	0	0	0	0	0
23:45	0	0	0	0	0
<b>TOTAL</b>	<b>13</b>	<b>21</b>	<b>1</b>	<b>21</b>	<b>56</b>

City: Costa Mesa  
 Location: Sunflower Avenue  
 Driveway: #3  
 Date: Wednesday 11 Sept 2019  
 Count Type: Driveway Classification

	Entering				Total
	Pass Veh	Large 2 Axle	3 Axle	4+ Axle	
0:00	0	0	0	0	0
0:15	0	0	0	0	0
0:30	0	0	0	0	0
0:45	0	0	0	0	0
1:00	0	0	0	0	0
1:15	0	0	0	0	0
1:30	0	0	0	0	0
1:45	0	0	0	0	0
2:00	0	0	0	0	0
2:15	0	0	0	0	0
2:30	0	0	0	0	0
2:45	0	0	0	0	0
3:00	0	0	0	0	0
3:15	0	0	0	0	0
3:30	0	0	0	0	0
3:45	0	0	0	0	0
4:00	0	0	0	0	0
4:15	1	0	0	0	1
4:30	1	0	0	0	1
4:45	0	0	0	0	0
5:00	0	0	0	0	0
5:15	0	0	0	0	0
5:30	0	1	0	0	1
5:45	0	0	0	0	0
6:00	1	0	0	0	1
6:15	0	0	0	0	0
6:30	0	0	0	0	0
6:45	0	0	0	0	0
7:00	0	0	0	0	0
7:15	0	0	0	0	0
7:30	0	0	0	0	0
7:45	0	0	0	0	0
8:00	0	0	0	0	0
8:15	0	0	0	0	0
8:30	0	0	0	0	0
8:45	0	0	0	1	1
9:00	1	1	0	0	2
9:15	0	1	0	0	1
9:30	0	0	0	1	1
9:45	0	0	0	0	0
10:00	0	0	0	2	2
10:15	0	1	0	0	1
10:30	0	1	0	0	1
10:45	2	2	0	0	4
11:00	1	2	0	1	4
11:15	1	0	0	0	1
11:30	0	1	0	0	1
11:45	0	0	0	0	0
12:00	0	1	0	0	1
12:15	0	1	0	1	2
12:30	0	1	0	0	1
12:45	0	0	0	0	0
13:00	0	0	0	0	0
13:15	0	0	0	0	0
13:30	0	0	0	0	0
13:45	0	0	0	0	0
14:00	0	0	0	0	0
14:15	0	0	0	0	0
14:30	0	0	0	0	0
14:45	0	1	0	0	1
15:00	0	0	0	0	0
15:15	1	0	0	0	1
15:30	0	0	0	0	0
15:45	0	0	0	0	0
16:00	0	0	0	0	0
16:15	0	0	0	0	0
16:30	0	0	0	0	0
16:45	0	0	0	0	0
17:00	0	0	0	0	0
17:15	0	0	0	0	0
17:30	0	0	0	0	0
17:45	0	0	0	0	0
18:00	0	0	0	0	0
18:15	1	0	0	0	1
18:30	0	0	0	0	0
18:45	0	0	0	0	0
19:00	0	0	0	0	0
19:15	0	0	0	0	0
19:30	0	0	0	0	0
19:45	0	0	0	0	0
20:00	0	0	0	0	0
20:15	0	0	0	0	0
20:30	0	0	0	0	0
20:45	0	0	0	0	0
21:00	0	0	0	0	0
21:15	0	0	0	0	0
21:30	0	0	0	0	0
21:45	0	0	0	0	0
22:00	0	0	0	0	0
22:15	0	0	0	0	0
22:30	0	0	0	0	0
22:45	0	0	0	0	0
23:00	0	0	0	0	0
23:15	0	0	0	0	0
23:30	0	0	0	0	0
23:45	0	0	0	0	0
<b>TOTAL</b>	<b>10</b>	<b>14</b>	<b>0</b>	<b>6</b>	<b>30</b>

	Exiting				Total
	Pass Veh	Large 2 Axle	3 Axle	4+ Axle	
0:00	0	0	0	0	0
0:15	0	0	0	0	0
0:30	0	0	0	0	0
0:45	0	0	0	0	0
1:00	0	0	0	0	0
1:15	0	0	0	0	0
1:30	0	0	0	0	0
1:45	0	0	0	0	0
2:00	0	0	0	0	0
2:15	0	0	0	0	0
2:30	0	0	0	0	0
2:45	0	0	0	0	0
3:00	0	0	0	0	0
3:15	0	0	0	0	0
3:30	0	0	0	0	0
3:45	0	0	0	0	0
4:00	0	0	0	0	0
4:15	1	0	0	0	1
4:30	0	0	0	0	0
4:45	0	0	0	0	0
5:00	0	0	0	0	0
5:15	0	0	0	0	0
5:30	0	0	0	0	0
5:45	0	0	0	0	0
6:00	0	0	0	0	0
6:15	0	0	0	0	0
6:30	0	1	0	0	1
6:45	0	0	0	0	0
7:00	0	0	0	0	0
7:15	0	0	0	0	0
7:30	0	0	0	0	0
7:45	0	0	0	0	0
8:00	0	0	0	0	0
8:15	0	0	0	0	0
8:30	0	0	0	0	0
8:45	1	0	0	0	1
9:00	0	0	0	0	0
9:15	0	0	0	0	0
9:30	0	0	0	1	1
9:45	0	2	0	1	3
10:00	0	0	0	1	1
10:15	0	0	0	0	0
10:30	1	1	0	0	2
10:45	0	2	0	0	2
11:00	2	1	0	0	3
11:15	0	1	0	0	1
11:30	0	0	0	1	1
11:45	0	1	0	0	1
12:00	0	1	0	0	1
12:15	0	0	0	0	0
12:30	1	0	0	2	3
12:45	0	2	0	0	2
13:00	0	0	0	0	0
13:15	1	0	0	0	1
13:30	0	1	0	0	1
13:45	0	0	0	0	0
14:00	0	0	0	0	0
14:15	0	0	0	0	0
14:30	0	0	0	0	0
14:45	0	0	0	0	0
15:00	0	1	0	0	1
15:15	1	0	0	0	1
15:30	0	0	0	0	0
15:45	0	0	0	0	0
16:00	0	0	0	0	0
16:15	0	0	0	0	0
16:30	1	0	0	0	1
16:45	0	0	0	0	0
17:00	0	0	0	0	0
17:15	0	0	0	0	0
17:30	0	0	0	0	0
17:45	0	0	0	0	0
18:00	0	0	0	0	0
18:15	0	0	0	0	0
18:30	1	0	0	0	1
18:45	0	0	0	0	0
19:00	0	0	0	0	0
19:15	0	0	0	0	0
19:30	0	0	0	0	0
19:45	0	0	0	0	0
20:00	0	0	0	0	0
20:15	0	0	0	0	0
20:30	0	0	0	0	0
20:45	0	0	0	0	0
21:00	0	0	0	0	0
21:15	0	0	0	0	0
21:30	0	0	0	0	0
21:45	0	0	0	0	0
22:00	0	0	0	0	0
22:15	0	0	0	0	0
22:30	0	0	0	0	0
22:45	0	0	0	0	0
23:00	0	0	0	0	0
23:15	0	0	0	0	0
23:30	0	0	0	0	0
23:45	0	0	0	0	0
<b>TOTAL</b>	<b>10</b>	<b>14</b>	<b>0</b>	<b>6</b>	<b>30</b>